

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 11890

RECEIVED FROM

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080062-5

PLANT #9

DATE REC'D 4-12-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO. S.O. NO.
	322		155	0	10				
15	DRAWING NO. AND DESCRIPTION					QUANTITY		REMARKS	
	731961 Cable Assy IHC Motor					15 ✓		Store	
128 5570									

M. E. Bender
J. L. [unclear]

RECEIVED BY *M. E. Bender* INSPECTED BY *[Signature]* DATE 4-12-57 REJECTS RETURNED ON SHIP MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 11898

RECEIVED FROM

251 S. COLORADO ST., PASADENA, CALIF.

DATE REC'D 4-12-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO. S.O. NO.
	322		154	0	10				
9	DRAWING NO. AND DESCRIPTION					QUANTITY		REMARKS	
	731960 Filter IHC M.T. MINE					9 ✓		Store	
128 5567									
Ordered before print change									

M. E. Bender
J. L. [unclear]

RECEIVED BY *M. E. Bender* INSPECTED BY *[Signature]* DATE *4-12-57* REJECTS RETURNED ON SHIP MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080062-5